

CALIFORNIA DIVISION OF MINES AND GEOLOGY

^{No. 3}
Supplement ₁ to FER-4

July 22, 1977

The following references were overlooked in the earlier evaluation of the Loma Linda fault. They were only partly checked, but they do not appear to provide information that would alter the basic conclusions drawn in the report of March 18, 1976.

4. Lists of references:

- s) Burnham, W.L., 1960, Geology and ground-water hydrology of the Redlands-Beaumont area, California, with special reference to ground-water flow: U.S. Geological Survey open file report, more than 262 pages with maps (scale 1:31,680?). (Portion of report is in Map Room file, San Bernardino Sheet.)
- t) Eckis, R., 1934, South coastal basin investigation: geology and ground water storage capacity of valley fill: California Division of Water Resources Bulletin 45, 279 p., 3 plates. (Not checked, but provides original data on ground-water barriers.)
- u) Miller, R.E., and Singer, J.A., 1971, Subsidence in Bunker Hill-San Timoteo area, southern California: U.S. Geological Survey, Open-File Report, 28 p. (Copy not in Library.)

E. Hart
4/22/77